

November 15, 2011

ROTAX
NEW AGE KARTING



GO ROTAX
Powered by the MAXSpeed Group
269.756.7444

BULLETIN

COIL EXCHANGE PROGRAM ("PIG-TAIL" COIL 265571) FOR ALL ROTAX ENGINES

Dear Rotax Customer,

Unfortunately rumors have been noticed concerning Rotax part no. 265571 "extension wire/pigtail" ignition coils having a perceived performance advantage.



To cure this situation, BRP-Rotax has decided that the ignition coils with extension wire will no longer be legal within the Rotax Max Challenge (RMC) regulations 2012 (valid as of January 1, 2012) for ALL engine classes (Micro, Mini, Junior and Senior).

To support those customers in possession of ignition coils with extension wires, BRP-rotax will offer an exchange campaign for these coils.

Within the defined timeframe of December 1, 2011 through April 30, 2012, customers can return the coils (marked with the number 265571 on the housing) to their ROTAX service centers/dealers which will exchange their ignition coil FREE OF CHARGE with a new ignition coil.

PLEASE NOTE: 265 578 does NOT include a spark plug cap!

EXCHANGE CAMPAIGN - IGNITION COILS 265 571

Timeframe: December 1, 2011 through April 30, 2012
Conditions: Exchange FREE of CHARGE

Regards,

www.GoRotax.com

maxspeed
GROUP
S.A.S. - www.GoRotax.com